Exhibit C

علون) 3)
Koro)
200	3

Bell Tex Estimate wt Tax, O&H on units

page 1 of 18

2014-013-4-30

The following described work on Walkers Cafe will effect the use of the dining and kitchen areas. Walkers cafe will continue to operate their normal business hours. This work will be carried out after

		normal business hours.						
<u>m</u>	2	5 City of Madisonville permit	-	\$400.00 \$400.00	\$400.00		\$400.00	\$400.00
∢ ∢	2	Remove and reset roof sheets after test Remove and reset Galvanized Metal Cap & Parapet Flashing 16+12 x 5	6+12 ×	ī.				
	Ø	Remove and reinstall Curb Flashing 47 If	: ! : !=		\$423.00	\$8.47	\$398.09	\$821.09
	Ω		<u>u</u>	\$2.00	\$54.00	\$1.12	\$30.24	\$84.24 905.33
· · · · · · · · · · · · · · · · · · ·		NOTE: Per Engineers request this inspection has not been completed. The unknown variables would lead to				8.25%s	8.25% sales tax	\$74.69
		a supplement for unknown repairs at this time.					10%0H	\$98.00
		See page 10 last paragraph of Structural assessment 5/30/14	S				10%P	\$1,078.02 \$107.80
								\$1,185.82
4	(n)	Detach and reset roof panels 3' x 26' and 29' long	٠,	\$4.70	\$280 50	\$0.50	4363.00	\$643.50

\$643.50	\$52.00 695.5	\$57.38 \$752.88	\$75.29	\$82.82 \$910.98
\$363.00	\$30.00	3.25% sales tax	10%OH	10%P
\$2.20	\$30.00	8.25%s		
\$280.50	\$22.00			
\$1.70	\$22.00			
165 sf	***			
3 Detach and reset roof panels 3' x 26' and 29' long a Remove and replace Metal Roofing -ribbed-24 ga	b Remove and replace metal roof jack			
⋖			· Carlo Director	

\$486.00	\$250.86 736.86	\$60,79 \$797.65	\$79.77	\$87.74
	\$41.81 \$250.86	ales tax	10%0H	10%P
	\$41.81	8.25% sales tax		
\$0.81 \$486.00				
\$0.81				
600 sf	6 hrs			
4 Heavy Tarp to Cover metal roof for inspection a Tarp all Purpose poly 20x30	b Temporary Repairs-General Labor-after hrs			
4 a	Ω			

							a	page 3 of 18
<u>U</u>	(Install shoring inside dining area						
)	٥	Remove contents in drining and knoteri areas a Manipulation of contents after hrs	4 hrs			\$27.84	\$111.36	\$111.36
ပ	^		kitchen			\$27 8A	X 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	# # # # #
***************************************	. —	a Scarrolding Setup & take down z aner/ins each b Scaffold-per section 5x5@2	2 per w	\$48.00	\$96.00	to: 170	0000	\$96.00
ပ	ω	Build Dust curtain in dining and kitchen area						
			286 sf	\$0.13	\$37.18	\$1.30	\$371.80	\$408.98
*************		b Striping and screws	20 lf	\$1.00	\$20.00	\$1.00	\$20.00	\$40.00
(•	7 hrs			\$41.81	\$292.67	\$292.67
<u>ပ</u>	න ි	Detach and reset ceiling tiles to allow shoring Remove and reinstall Tin Ceiling Panel	96 Sf		\$3.809.61	\$2.00	\$192.00	\$4,001.61
**************************************			les created for t stripping.		·			
ပ	9	Remove and replace Insulation above ceiling tiles						
	- =	a Remove and replace Insulation	80 sf	\$1.20	\$96.00	\$1.85	\$148.00	\$244.00
<u>U</u>		Install and remove shoring of ceiling joist					1	
e;		_	72 If	\$2.06	\$148.32	\$0.00	\$0.00	\$148.32
		_	24 pcs	\$28.84	\$692.16		\$0.00	\$692.16
***************************************			4 pcs	\$13.68	\$54.72	i		\$54.72
		d Carpenter After hrs	7 hrs 7 hrs			\$27.84 \$27.84	\$194.88 \$194.88	\$194.88 \$194.88
) !)) :)	\$6,535.26
***************************************						8.25%	8.25% sales tax	\$539.16
<i>-</i>							10%0H	\$707.44
·····							, C	67.70
***************************************							٦. ٥	\$8,560.05
_	ļ							

Days + 01 10		\$69.00	\$69.00	\$111.88	\$111.88	\$251.36	\$251.36	\$864.48	\$71.32	\$935.80	\$93.58	\$1,029.38	\$102.94	\$1,132.32
		\$51.00	\$51.00	\$80.00	\$80.00	\$80.00	\$80.00		ales tax		10%0H		10%P	
	<u> </u>	\$4.25	\$4.25	\$20.00	\$20.00	\$20.00	\$20.00		8.25% sales tax					
	er hours	\$18.00	\$18.00	\$31.88	\$31.88	\$171.36	\$171.36							
	ation (aft	\$1.50	\$1.50	\$7.97	\$7.97	\$42.84	\$42.84							
	iling and insulation installation (after hours)	12 If	12 If	4 hrs	4 hrs	4 hrs	4 hrs							
	C # Clean work area after ceiling and in	a Clean bar contents after shoring installed	Clean bar contents after shoring removed	 b Labor to clean after shoring installed 	Labor to clean after shoring removed		HEPA Vacuuming after shoring removed)						
	井	Ø		Ω,		ပ								

item Description	Onty type unit	nit I	Material	unit	Labor	subtotal
C # Paint Dining/Kitchen ceiling						
a Ceiling tiles 25x78.66 @ 13' AFF	1966.5 sf	\$0.50	\$983.25	\$1.50	\$1.50 \$2,949.75	\$3,933.00
2 jabors 8hrs	16 hrs			\$27.84	\$445.44	\$445.44
c Temporary storage 8x40	1 wk	\$245.00	\$245.00			\$245.00
	2 hr			\$27.84	\$55.68	\$55.68
e Scaffold-per section 5x5@2	2 per w	\$48.00	\$96.00			00'96\$
NOTE: Cleaning of ceiling tiles is not included may have				8.25%	8.25% sales tax	\$4,775.12 \$393.95
to supplient:	1					\$5,169.07
					10%0H	
						\$5,685.97
					10%P	\$568,60
						\$6,254.57

C # Clean work area after painting ceiling a Clean bar contents b Labor to clean 3 labors 6 hrs each c HEPA Vacuuming c HEPA Vacuuming 8.257.04 8.25%	page 5 of 18	\$323.00 \$437.00			\$1,197.50	8.25% sales tax \$98.79	\$1,296.29	10%OH \$129.63	\$1,425.92	10%P \$142.59	\$1,568.52
inting ceiling 76 lf \$1.50 18 hrs \$7.97 6 hrs \$42.84		\$4.25	\$20.00	\$0.00		8.25%					
inting ceiling 76 lf 18 hrs 6 hrs		\$114.00	\$143.46	\$257.04							
inting ceiling		\$1.50	\$7.97	\$42.84							
# Clean work area after painting ceiling a Clean bar contents b Labor to clean 3 labors 6 hrs each c HEPA Vacuuming		76 If	18 hrs	6 hrs							
	4 Close work area affer nainting coiling	a Clean bar contents	b Labor to clean 3 labors 6 hrs each	c HEPA Vacuuming							

	0	d	5 O	0	ထ	ω	ω	ဖ
	\$150.0	890.0	\$240.00 \$19.80	\$259.8	\$25.9	\$285.7	\$28.5	\$314.3
		\$90.00	8.25% sales tax		10%0H		10%P	
	\$25.00	\$15.00	8.25%					
Canopy Remove temporary walls on sidewalk under canopy	6 hrs	6 hrs						
1	a Carpenter	b Labor						
#	10							

page 6 of 18	\$39.00	\$42.22	\$4.22	\$4.64	
pa	\$33.00	les tax	10%0H	10%P	
	\$6.00 \$33.00	8.25% sales tax			
	\$6.00				
der canopy	\$6.00				
Detach and reset 4' Fluorescent light fixture under canopy	a Remove and reinstall Fluorescent light fixture				
#	o	upung.	ankinduki ida	amente e e e e e e e e e e e e e e e e e e	

m
48 sf \$1.40 \$6

E 18 Set up scaffolding for work to remove brick after canopy sheets are removed Scaffolding Setup & take down 4 per w \$48.00 \$192.00 F 19 Remove and replace 5' of Wythe solid brick wall from the top of the steel lintel a Remove and reinstall 3 layers of brick5x89"x3 Remove and reinstall 3 layers of brick brick fat washer and nuts into new wall A units \$10.00 \$43.30 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$40.00 \$20.00 \$80.00 ROTE: Page 10 last paragraph of Structural Assessment Action \$40.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.00 \$10.								
Scaffold-per section 5x5 Remove and replace 5' of Wythe solid brick wall from the top of the steel lintel Remove and replace 5' of Wythe solid brick wall from the top of the steel lintel Remove and reinstall 3 layers of brick5x8'9"x3 415 sf \$15.04 \$6,241.60 \$15.00 \$6,225 a Saw cut brick (Tooth) 3-Wythe brick joint Bennote and reinstall 3 layers of brick5x8'9"x3 8.66 lf \$5.00 \$43.30 \$25.00 \$216 b Englineer shall verify in field the extent of distress to the brick facade prior to issuance of repair documents c Install joint reinforcing with 9 ga. 130 truss-tri-mesh @ every 4th course as manufactured by Hohmann & Barn or approved equal. Construct to match existing d Install 4 - 3/4" round x 10" long boits with 3" x 3" x 1/4" thick flat washer and nuts into new wall 3/4"x10"bolts wt 3" x 3" x 1/4" washer/nuts NOTE: Page 10 last paragraph of Structural Assessment dated 5/30/14. "CRA can verify conditions and extent of distress of the solid brick wall above Walkers Cafe". This may change the repair recommendations and a supplement may be required.	Scattolding Setup & 1	work to remove brick after canop) ake down	/ sheets are rem 4 hr	loved		\$45.00	\$180.00	\$180.00
Remove and replace 5' of Wythe solid brick wall from the top of the steel lintel a Remove and replace 5' of Wythe solid brick wall from the top of the steel lintel a Remove and reinstall 3 layers of brick5x8'9"x3 415 sf \$15.04 \$6,241.60 \$15.00 \$216 a Saw cut brick (Tooth) 3-Wythe brick joint b Engineer shall verify in field the extent of distress to the brick facade prior to issuance of repair documents c Install 4 - 3/4" round x 10" long bolts with 3" x 3" x 1/4" thick flat washer and nuts into new wall or approved equal. Construct to match existing d Install 4 - 3/4" round x 10" long bolts with 3" x 3" x 1/4" thick flat washer and nuts into new wall 3/4"x10"bolts wt 3" x 3" x 1/4" washer/nuts NOTE: Page 10 last paragraph of Structural Assessment dated 5/30/14. "CRA can verify conditions and extent of distress of the solid brick wall above Walkers Cafe". This may change the repair recommendations and a supplement may be required.)X5	4 per w	\$48.00	\$192.00			\$192.00
Saw cut brick (Tooth) 3-Wythe brick joint 8.66 If \$5.00 \$43.30 \$25.00 \$216 Engineer shall verify in field the extent of distress to the brick facade prior to issuance of repair documents Install joint reinforcing with 9 ga. 130 truss-tri-mesh @ every 4th course as manufactured by Hohmann & Barn or approved equal. Construct to match existing 40 If \$4.00 \$160.00 \$2.00 \$80 Install 4 - 3/4" round × 10" long bolts with 3" × 3" × 1/4" thick flat washer and nuts into new wall 3/4"×10" bolts wt 3" × 3" × 1/4" washer/nuts 4 units \$10.00 \$40.00 \$20.00 \$80 NOTE: Page 10 last paragraph of Structural Assessment dated \$130/14. "CRA can verify conditions and extent of distress of the solid brick wall above Walkers Cafe". This may change the repair recommendations and a supplement may be required. a supplement may be required.	Ø	5' of Wythe solid brick wall from th 3 layers of brick5x8'9"x3	ne top of the stee 415 sf	el lintel \$15.04	\$6,241.60	\$15.00	\$6,225.00	\$12,466.60
Engineer shall verify in field the extent of distress to the brick facade prior to issuance of repair documents Install bint reinforcing with 9 ga. 130 truss-tri-mesh @ every 4th course as manufactured by Hohmann & Barn, or approved equal. Construct to match existing 40 lf \$4.00 \$160.00 \$2.00 \$80 Install 4 - 3/4" round x 10" long bolts with 3" x 3" x 1/4" thick flat washer and nuts into new wall 3/4"x10"bolts wt 3" x 3" x 1/4" washer/nuts 4 units \$10.00 \$40.00 \$20.00 \$80 NOTE: Page 10 last paragraph of Structural Assessment 4 units \$10.00 \$40.00 \$20.00 \$80 dated \$130/14. "CRA can verify conditions and extent of distress of the solid brick wall above Walkers Cafe". This may change the repair recommendations and a supplement may be required.		3-Wythe brick joint	8.66 If	\$5.00	\$43.30	\$25.00	\$216.50	\$259.80
unsaturations (2 of 5 of		n field the extent of distress to the	brick facade pri	or to issua	nce of repai	ir docume Johmann	nts 8. Bamand	
with 3" × 3" × 1/4" thick flat washer and nuts into new wall sr/nuts 4 units \$10.00 \$40.00 \$20.00 \$80 \$10.0		with a gar. 130 truss-tri-friesh (@ sonstruct to match existing	yery tur course 40 lf	\$4.00	\$160.00	\$2.00	\$80.00	\$240.00
strinuts 4 units \$10.00 \$40.00 \$20.00 \$800 \$800 \$1000	3 d Install 4 - 3/4" round >	< 10 " long bolts with 3" \times 3" \times 1/4"	thick flat washer	r and nuts	into new wa	=		
8.25%sales ta	3/4"x10"bolts wt 3" x	3" x 1/4" washer/nuts	4 units	\$10.00	\$40.00	\$20.00	\$80.00	\$120.00
8.25% sales ta								\$13,458.40
	NOTH: Page 10 last	paragraph of Structural Assessi	ment			8.25%	sales tax	\$1,110.32
il above Walkers Cafe". ommendations and	dated SOSTA. "CIV	can verify conditions and exter	birds said said					\$14,568.72
ommendations and	of distress of the so	lid brick wall above Walkers Ca	, j				10%OH	\$1,456.87
	This may change th	e repair recommendations and						\$16,025.59
	a supplement may b	e required,					10%P	\$1,602,56
								\$17,628.15

ork areas Daily 76 If \$1.50 \$114.00 \$4.25 \$323.00 \$437.00 \$223.76 \$20.00 \$160.00 \$223.76 \$223.76 \$20.00 \$80.00 \$223.76 \$912.12 \$912.12 \$8.25% sales tax \$987.37 \$1,086.11 \$10% P \$1,086.11 \$1194.72	\$1.50 \$114.00 \$4.25 \$323 \$7.97 \$63.76 \$20.00 \$160 \$ \$42.84 \$171.36 \$20.00 \$80 8.25%sales ta							
y 76 lf \$1.50 \$114.00 \$4.25 \$323.00 8 hrs \$7.97 \$63.76 \$20.00 \$160.00 4 hrs \$42.84 \$171.36 \$20.00 \$80.00 10%OH	y 76 lf \$1.50 \$114.00 \$4.25 \$323 8 hrs \$7.97 \$63.76 \$20.00 \$160 4 hrs \$42.84 \$171.36 \$20.00 \$80 8.25% sales ta							
76 If \$1.50 \$114.00 \$4.25 \$323.00 8 hrs \$7.97 \$63.76 \$20.00 \$160.00 4 hrs \$42.84 \$171.36 \$20.00 \$80.00 8.25% sales tax 10% OH	76 lf \$1.50 \$114,00 \$4.25 \$323 8 hrs \$7.97 \$63.76 \$20.00 \$160 \$160 \$41.84 \$171.36 \$20.00 \$80 \$100 \$100 \$100 \$100 \$100 \$100 \$10	work areas Daily						
\$ \$7.97 \$63.76 \$20.00 \$160.00 \$ \$42.84 \$171.36 \$20.00 \$80.00 8.25% sales tax 10% OH	\$ \$7.97 \$63.76 \$20.00 \$160 \$ \$42.84 \$171.36 \$20.00 \$80 8.25% sales ta		76 If	\$1.50	\$114.00	\$4.25	\$323.00	\$437.00
\$42.84 \$171.36 \$20.00 \$80.00 8.25%sales tax 10%OH	\$42.84 \$171.36 \$20.00 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$		8 hrs	\$7.97	\$63.76	\$20.00	\$160.00	\$223.76
HO%6	8.25% sales tax 16.25%		4 hrs	\$42.84	\$171.36	\$20.00	\$80.00	\$251.36
%ОН %Р	8.25% sales tax							\$912.12
I.	*** **					8.25%s	ales tax	\$75.25
I	¥ ¥							\$987.37
	~						10%OH	\$98.74
	T							\$1,086.11
\$1,194.72							10%P	\$108.61
								\$1,194.72

ш		Construction						
Ш	#	Install Shear Panel per Detail 3						eleterkeni viite
7	a	21 a Install solid 4x6 blocking frimmed to fit between existing rafters, nail 10D @ 6" O.C. into Blocking thru existing decking	ers, nail 10Ľ	0.0 "> @	; into Block	ing thru ex	risting decking	
e pê panas,		4x6-12'@2	24 If	\$23.89	\$573.36 \$40.00	\$40.00		\$1,533.36
<i>α</i>	<u>ح</u>	21 b Install 4 x 4 x 8'-6" minimum top and bottom as shown with Simpson 2 - LTT20B with 4 - 3/4" thru-bolt at brick wall and 2	Simpson 2	- LTT20B v	vith 4 - 3/4"	thru-bolt a	at brick wall and 2	ar yan da af fan
		4x4x10	2 pcs	\$11.75	\$23.50	\$40.00	\$80.00	\$103.50
,		LTT20B	2 units	\$20.00	\$40.00	\$20.00	\$40.00	\$80.00
		1/2"x 10" round thru bolts, nuts & washers	4 unit	\$10.00	\$40.00	\$5.00	\$20.00	\$60.00
		3/4" x 18" thru-bolt, nut and washers	2 units	\$16.00	\$32.00	\$20.00	\$40.00	\$72.00
7	10	21 c Install Simpson TP35 - 2 per block w/ 3 -NB EA member alternate sides	ernate sides					umotilh
		Simpson TP35	8 units	\$4.00	\$32.00	\$20.00	\$160.00	\$192.00
7	21 d	Install 10D @ 6' O.C. into Blocking	8 units	\$2.00	\$16.00	\$20.00	\$160.00	\$176.00
7	-	Install 2x4 EA. side of existing Diagonal 9x8	72 If	\$2.06	\$148.32	\$5.00	\$360.00	\$508.32
~	21 g	Install H3 clips Top and Bottom of 2x4 to new 4x4	10 units	\$5.00	\$50.00	\$5.00	\$50.00	\$100.00
-7	<u></u>	h Install 2x4 blocking typically between 2x4s and nail wt 2-16D 12" O.C. Staggered each side typically	0 12" O.C. S	taggered e	each side ty	pically		
		2x4-8'	40 lf	\$2.06	\$82.40	\$5.00	\$200.00	\$282.40
7	7	Install H3 clips from new 4x4 to existing joist	10 units	\$5.00	\$50.00	\$5.00	\$50.00	\$100.00
7	21 K	Install 15/32 thick structural 1 plywood shear panels on one side w/10D @ 6" O.C. all edges, notch plywood @ existing rafters	side w/10D	@ 6" O.C.	all edges, r	notch plyw	ood @ existing rafters	(A
***************************************		structural 1 plywood shear panel	1 pc	\$350.00	\$350.00	\$40.00	\$40.00	\$390.00

\$437.00 \$223.76 \$251.36	\$476.08 \$476.08 \$6.246.78	\$624.68	\$687.15 \$687.15 \$7,558.61			\$125.00	\$30.90	\$6.87	\$121.73	\$7.25	\$7.57	\$250.00 \$120.00	701.88	\$57.91 \$759 79	\$75.98	\$83.58	\$919.34
\$323.00 \$160.00 \$80.00	8.25% sales tax	10%OH	10%P	:	sidewalk and entrance	\$25.00	•					\$250.00 \$120.00		8.25% sales tax	10%0H	10%P	
\$4.25 \$20.00 \$20.00	8.25%s				lk and 6	\$25.00						\$25.00 \$15.00		8.25%			
\$114.00 \$63.76 \$171.36						\$125.00	\$30.90	\$6.87	\$121.73	\$7.25	\$7.57						
\$1.50 \$7.97 \$42.84					glass on	\$125.00	\$3.09	\$2.29	\$17.39	\$7.25 \$1.89	\$7.57						
Daily 76 If 8 hrs 4 hrs		rendations.			strians and		. 6	1 რ	,	~ 4	₩.	€ ∞	•				
Clean work construction area in dining room Daily a Clean bar contents b Labor to clean c HEPA Vacuuming	MOTH: This repairing Engineer Specific Pa 4-6	of attachment "F" of the conceptual repair recommendations.	Ty i of same anatoment, adminoral vermanon is required. Therefore a supplement may be required.		Install and remove Protection for pedestrians	 a Charges for scaffolding as needed to access ceiling b Charges to set up and secure scaffolding 	c 2x4x8 #2 Yellow Pine		e 4x8x3/8 CD Yellow Pine	t 1x5x8 #2 Yellow Pine g 1x2x8 #2 Yellow Pine		i Carpenter Labor					
# 	and an internation to the	to have bloken to	satera=mszatssat		#		26	26	58	% % %	26	88	Ì	•			

	\$437.00	\$223.76	\$251.36	912.12	\$75.25	\$987.37	\$98.74	\$1,086.11	\$108.61	\$1,194.72
	\$323.00	\$160.00	\$80.00		8.25% sales tax		10%OH		10%P	
entran	\$4.25	\$20.00	\$20.00		8.25%s					i
valk and	\$114.00	\$63.76	\$171.36							
on sidev	\$1.50	\$7.97	\$42.84							
or pedestrians and glass on sidewalk and entrance	\$76.00 If	\$8.00 hrs	\$4.00 hrs							
for pedestri	•									
Clean construction area for	a Clean bar contents	b Labor to clean	HEPA Vacuuming)						
# 	m	Ω.	O							and the first financing to be accompany to

<u>ш</u>	1				:		
item	Description	Onty type unit		naterial L	nit	Labor	subtotal
28 田		384 sf	\$0.50	\$192.00	\$0.75	\$288.00	\$480.00
	Seal brick with masonry sealer	147 SF	\$0.64	\$94.08		\$110.25	\$204.33
Ø						,	
	b Scaffolding Setup & take down	2 hr			\$27.84	\$55.68	\$55.68
U	c Scaffold-per section 5x5	2 per w	\$48.00	\$96.00		\$96.00	296.00
							\$836.01
					8.25%s	8.25% sales tax	268.97
							\$904.98
						10%OH	\$90.50
							\$995.48
						10%P	\$99.55
							\$1,095.03

_ (Ó	_	ဖွ	ဖွ	o	ထွ	Ņ	Ñ	۱ [<u> </u>	o	Ō	o	0	က	က္
page 12 of 10	3145.0	\$145.00	\$11.9	\$156.9	\$15.7	\$172.6	\$17.2	189.9			3400.0	\$33.0	5433.0	843.3	3476.3	\$47.6	\$523.93
zi ane	03	07		07		97		47			07		07		0 7		47
Ď.					HO		<u>а</u>							H		<u>а</u> .	
			tax		10%OH		10%P				320.00	tax	,	10%OH		10%P	
			8.25% sales tax								\$80.00 \$320.00	8.25% sales tax					
			8.25								\$80.0	8.25					
	145										\$80.00						
	145										\$20.00						
	1 mo										4 hr						
	ilet									_							
	y To									Sign	teset						
	oorar									ness	and F						
	Temporary Toilet									Business Sign	Detach						
	•										Ø						
	Ц.	-	<i></i>	برسيم				new partners		ഗ		·	******			*********	· /····

Fam Description Labor Labor Labor Labor Labor Subtotal Labor Labor Subtotal Labor		: :- : : : : : : : : : : : : : : : : :						page 15 of 18
Personation	~	Dining Celling replacement (From Insu	rance inspe	ction)				
Remove contents in dining and kitchen areas 2 hr. Set up scaffolding to install dust Curtain in dining and kitchen a scaffolding setup & take down 2 afterfurs each b Scaffold-per section 5x6@2 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents after curtin new tiles created for this project. NOTE: The celling panels NOTE:	iten			Ħ		unit	Labor	subtotal
Set up scaffolding to install dust Curfain in dining and kitchen Scaffolding Setup & Istale down 2 afterfure each NOTE: Tin ceiling files will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. Remove and replace Insulation above ceiling tiles Action work area after cuttin installed Clean work area after cuttin installed Clean bar contents after cuttin installed	~	Remove contents in dining and kitchen areas						
Set up scaffolding to install dust Curtain in dining and kitchen Set up scaffolding to install dust Curtain in dining and kitchen Scaffold-per section 8x6@2 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 384 sf \$0.13 \$49.92 \$1.30 \$499.20 8 hrs Reset celling tiles a Reinstall Tin Celling tiles A Reset celling tiles A Remove and replace Insulation above celling tiles A Remove and re		a Manipulation of contents after hrs	2 hrs			\$27.84		\$55.68
a Scaffolding Setup & take down 2 after/hrs each b Scaffolding Setup & take down 2 after/hrs each b Scaffold-per section 5x620 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 9+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 9+8x12 Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 9+8x12 Striping and screws C Temporary Repairs-General Labor-after hrs Reset Ceiling Ities Reset Ceiling Ities Reset Ceiling Ities will be replaced with new tiles created for this project. NOTE: The ceiling tiles will be replaced with new tiles created for this project. NOTE: The ceiling tiles will be replaced with new tiles created for this project. NOTE: The ceiling and insulation above ceiling tiles Remove and replace Insulation above ceiling tiles Remove and replace Insulation above ceiling tiles Remove and replace Insulation installed Clean work area after cuttin removed Clean work area after cuttin removed Clean work area after cuttin installed Clean work area after cuttin removed Clean bar contents after cuttin removed Clean bar contents after cuttin removed Clean bar contents after cuttin removed CHEPA Vacuuming after cutt	ス	Set up scaffolding to install dust Curtain in di	ning and kitch	eu				
b Scaffold-per section 5x6@2 Build and Remove Dust curtain in dining and kitchen area Build and Remove Dust curtain in dining and kitchen area Build and Remove Dust curtain in dining and kitchen area Build and Remove Dust curtain in dining and kitchen area Build and Remove Dust curtain in dining and kitchen area Build and Remove Dust curtain in dining and service a service of the set of		a Scaffolding Setup & take down 2 after/hrs each	2 hr			\$27.84		\$55.68
Build and Remove Dust curtain in dining and kitchen area a Protect contents poly 8+8x12 a Protect contents poly 8+8x12 b Striping and screws c Temporary Repairs-General Labor-after hrs b Striping and screws c Temporary Repairs-General Labor-after hrs A Reset ceiling tiles a Reinstail Tin Ceiling panels NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles are nailed to existing wood stripping. 5 Remove and replace Insulation above ceiling tiles a Remove and replace Insulation above ceiling tiles a Remove and replace Insulation Clean work area after curtin installed Clean work area after curtin removed Clean after curtin installed Clean after curtin installed Clean after curtin installed Clean strip tiles CHEPA Vacuuming after curtin installed CHEPA Vacuuming after curtin removed CHEPA Vacuuming after curtin remove		b Scaffold-per section 5x5@2	2 per w	\$48.00	\$96.00			\$96.00
a Protect contents poly 8+8x12 b Striping and screws c Temporary Repairs-General Labor-after hrs 8 hrs material price included a Reinstall Tin Ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: To ceiling tiles will be replaced with new tiles created for this project. NOTE: To ceiling tiles will be replaced with new tiles created for this project. NOTE: To ceiling tiles will be replaced with new tiles created for this project. NOTE: To ceiling tiles are nailed to existing wood stripping. S Remove and replace Insulation 16 sf \$1.00 \$16.00 \$2.00 \$32.00 Clean work area after cutin installed tiles and insulation installed tiles and the stripping tiles are nailed to elem after cutin installed bus to clean after cutin installed tiles and the stripping tiles are nailed to elem after cutin installed tiles and the stripping tiles are nailed to elem after cutin installed tiles and the stripping tiles are nailed to elem after cutin installed tiles and the stripping tiles are nailed to elem after cutin installed tiles and the stripping tiles are nailed to elem after cutin installed tiles and tiles are nailed to elem after cutin installed tiles are stripping tiles are nailed to elem after cutin installed tiles are stripping tiles are nailed to elem after cutin installed tiles are stripping tiles are nailed tiles are stripping tiles are nailed tiles are stripping tiles are nailed to elem after cutin installed tiles are stripping tiles are nailed to elem after cutin installed tiles are stripping tiles are nailed tiles are		Build and Remove Dust curtain in dining and	kitchen area					
b Striping and screws c Temporary Repairs-General Labor-after hrs Reset ceiling tiles Reset ceiling tiles Reset ceiling tiles Reinstall Trin ceiling Panels NOTE: The ceiling tiles are nailed to existing wood stripping. Remove and replace Insulation above ceiling tiles Remove and replace Insulation above ceiling tiles Remove and replace Insulation 16 sf \$1.00 \$16.00 \$64.00 Remove and replace Insulation 16 sf \$1.00 \$16.00 \$32.00 Clean work area after ceiling and insulation installed Clean work area after curtin installed Clean bar contents after curtin removed Clean ba			384 sf	\$0.13	\$49.92	\$1.30		\$549.12
4 Reset ceiling tiles 16 sf in D4a \$41.81 \$334.48 4 Reset ceiling tiles 16 sf in D4a \$4.00 \$64.00 8 Reinstall Tin Ceiling Panels 16 sf in D4a \$4.00 \$64.00 NOTE: Tin Ceiling tiles will be replaced with new tiles created for this project. 8.00 \$5.00 \$5.00 5 Remove and replace Insulation above ceiling tiles 16 sf \$1.00 \$16.00 \$2.00 \$32.00 6 Clean work area after ceiling and insulation installation (after hours) a Remove and replace Insulation after ceiling and insulation installation (after hours) \$6.00 \$4.25 \$170.00 a Clean work area after ceiling and insulation installation (after hours) \$6.00 \$4.25 \$170.00 a Clean work area after curtin installed 6 hrs \$7.57 \$4.25 \$170.00 b Labor to clean after curtin removed 6 hrs \$7.97 \$47.82 \$20.00 \$120.00 Labor to clean after curtin removed 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 Labor to clean after curtin removed 6 hrs \$42.84 \$257.04 \$20.00		b Striping and screws	32 If	\$1.00	\$32.00			\$64.00
## Reset ceiling tiles ## Reset ceiling tiles ## Reset ceiling tiles ## Reinstall Tin Ceiling Panels ## NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. ## NOTE: Tin ceiling tiles are nailed to existing wood stripping. ## NOTE: Tin ceiling tiles are nailed to existing wood stripping. ## NOTE: Tin ceiling tiles are nailed to existing wood stripping. ## NOTE: Tin ceiling tiles are nailed to existing wood stripping. ## Remove and replace Insulation above ceiling tiles ## Remove and Remove		c Temporary Repairs-General Labor-after hrs	8 hrs					\$334.48
a Reinstall Tin Ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles are nailed to existing wood stripping. Remove and replace Insulation above ceiling tiles a Clean work area after ceiling and insulation installed Clean bar contents after curtin installed b Labor to clean after curtin removed c HEPA Vacuuming after curtin installed c HEPA Vacuuming after curtin removed c HEPA Vacuuming after cur	不 4	Reset ceiling tiles		mate	rial price inc	Inded		
NOTE: Tin ceiling tiles will be replaced with new tiles created for this project. NOTE: Tin ceiling tiles are nailed to existing wood stripping. Remove and replace Insulation above ceiling tiles a Remove and replace Insulation 16 st 0.00 \$1.00 \$32.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$4.25 \$170.00 5.150 \$60.00 \$120.00 5.150 \$60.		a Reinstall Tin Ceiling Panels	16 sf		in D4a	\$4.00		\$64.00
a Remove and replace Insulation 6 Clean work area after ceiling and insulation installation (after hours) a Clean work area after cuttin installed a Clean bar contents after cuttin removed Character after a	Ω	NOTE: Tin ceiling tiles will be replaced with new tin NOTE: Tin ceiling tiles are nailed to existing wood Remove and replace Insulation above ceiling	les created for t stripping. I tiles	nis proje	**************************************			
6 Clean work area after ceiling and insulation installation (after hours) a Clean bar contents after curtin installed Clean bar contents after curtin installed b Labor to clean after curtin installed c HEPA Vacuuming after curtin removed c HEPA Vacuuming after curtin removed c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed d hrs \$42.84 \$257.04 \$20.00 \$120.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$257.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84 \$227.04 \$20.00 c HEPA Vacuuming after curtin removed e hrs \$42.84		Remove and replace Insulation		\$1.00	\$16.00	\$2.00		\$48.00
Clean bar contents after curtin installed Clean bar contents after curtin removed Clean bar contents after curtin removed Clean bar contents after curtin removed Labor to clean after curtin installed Labor to clean after curtin installed Clean bar contents after curtin installed Clean after		Clean work area after ceiling and insulation i	nstallation (aft	er hours	~			
d 40 if \$1.50 \$60.00 \$4.25 \$170.00 6 hrs \$7.97 \$47.82 \$20.00 \$120.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 \$120.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 \$3 \$120.00 \$120.00 \$120.00 \$3 \$120.00 \$120.00 \$3 \$120.00 \$120.00 \$3 \$12		Clean bar contents after curtin install	40 If	\$1.50	\$60.00	\$4.25		\$69.00
6 hrs \$7.97 \$47.82 \$20.00 \$120.00 6 hrs \$7.97 \$47.82 \$20.00 \$120.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 8.25%sales tax 10%OH \$10%P		Clean bar contents after curtin removed	40 if	\$1.50	\$60.00			\$69.00
6 hrs \$7.97 \$47.82 \$20.00 \$120.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 8: 8.25%sales tax \$5 10%OH \$5			6 hrs	\$7.97	\$47.82			\$167.82
6 hrs \$42.84 \$257.04 \$20.00 \$120.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 8.25%sales tax 10%OH \$5		Labor to clean after curtin removed	6 hrs	\$7.97	\$47.82			\$167.82
6 hrs \$42.84 \$257.04 \$20.00 \$120.00 \$3.25		c HEPA Vacuuming after curtin installed	6 hrs	\$42.84	\$257.04			\$251.36
0%0H 0%P		HEPA Vacuuming after curtin removed	6 hrs	\$42.84	\$257.04	\$20.00		\$251.36
1%0H 0%P								\$2,243.32
I						8.25%	sales tax	\$185.07
							10%C	
								\$2,671.23
\$2,938.36							10%F	
								\$2,938.36

Secondaries after his Secondaries Secondaries
\$245.00 \$245.00 material price included in D4a \$4.00 \$64.00 \$0.50 \$2.00 \$8.00 \$0.50 \$0.50 \$2.00 \$1.50 \$624.75 \$0.50 \$1.43.46 \$20.00 \$360.00 \$120.00
in D4a \$4.00 \$64.00 \$0.50 \$2.00 \$2.00 \$8.00 \$0.50 \$208.25 \$1.50 \$624.75 pe unit Material unit Labor subt \$ \$7.97 \$143.46 \$20.00 \$360.00 \$ \$42.84 \$257.04 \$20.00 \$120.00 10%OH
4 sf \$0.50 \$2.00 \$8.00 3.5 sf \$0.50 \$208.25 \$1.50 \$624.75 4ype unit Labor subt 18 hrs \$7.97 \$143.46 \$20.00 \$360.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 8.25% sales tax 10% OH
type unit Material unit Labor subt 18 hrs \$7.97 \$143.46 \$20.00 \$360.00 6 hrs \$42.84 \$257.04 \$20.00 \$120.00 8120.00 10%OH 10%OH 10%P
\$7.97 \$143.46 \$20.00 \$360.00 \$42.84 \$257.04 \$20.00 \$120.00 8.25%sales tax 10%OH
жон %Р
I

					Dad	page 15 of 18
Σ	Dumpster					
nonfinim.	40 CY Dumpster	1 load	\$650.00	\$650.00		\$650.00
					8.25% sales tax	\$53.63
********						\$703.63
					10%OH	\$70.36
						\$773.99
					10%P	\$77.40
						\$851.39

** NOTE;** B5 \$400.00 is not included in this total

Z		Supplemental Structural Repairs							
Z		Install shoring inside dining area							CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	item	Description	Onty	type unit	M	Material	unit	Labor	subtotal
Z	_	Remove contents in dining and kitchen areas	ı						N (600)
	w	Manipulation of contents after hrs	4 hrs	ភ			\$27.84	\$111.36	\$111.36
Z	7	Set up scaffolding to install dust Curtain in dining and kitchen	l kitchen						
· / • • • • • · · · · · · · · · · · · ·	w	Scaffolding Setup & take down 2 after/hrs each	inc C7 h	<u>_</u>			\$27.84	\$55.68	\$0.00
	Ω	Scaffold-per section 5x5@2		perw \$4	\$48.00	\$96.00			\$0.00
Z	ო	Build Dust curtain in dining and kitchen area							
and and a second	a		-286 s	4					
-1 m1/1 for		Protect contents poly 12+10x13	286 sf	4-					
e et et et et e		Protect contents poly 27.5 x10	357.5 sf	ų,					
den egnadan		•	643.5 sf		0.13	\$83.66	\$1.30	\$836.55	\$920.21
	Ω	b Striping and screws	78 If		\$1.00	\$78.00	\$1.00	\$78.00	\$156.00
	ပ	Temporary Repairs-General Labor-after hrs	6 hrs	<u>S</u>			\$41.81	\$250.86	\$250.86

	II II ishidah Saludishi ilahudan suuruunuda uungungg	\$2,090.40		\$5,397.21	\$545.95	\$148.32 \$692.16 \$339.90 \$692.16 \$27.36 \$334.08
page 16 of 18		\$2,0		ග ින හි	()	# # # # # # # # # # # # # # # # # # #
		\$312.00		\$728.00	\$331.15	\$0.00 \$0.00 \$0.00 \$0.00 \$334.08
		\$8.00		\$8.00	\$1.85	\$0.00 \$0.00 \$27.84 \$27.84
		\$1,778.40		\$4,669.21	\$214.80	\$148.32 \$692.16 \$339.90 \$692.16 \$27.36
\$600.00		\$45.60	\$51.31	\$51.31	\$1.20	\$2.06 \$28.84 \$2.06 \$28.84 \$13.68
shoring -96 sf 35 pcs	2.7 pcs 2.7 pcs 6 pcs 45 pcs	39 pcs	15 pcs 11 pcs 4 pcs	95 pcs 91 pcs kripping.	179 sf	72 If 21 pcs 165 If 24 pcs 2 pcs 12 hrs 12 hrs
Detach and replace ceiling tiles to allow access and shoring Remove and reinstall Tin Ceiling Panel in C9 Custom Ceiling Tile Order includes: Replication fee Base Order Custom 2x2 to match existing Base Order Custom 2x2 to match existing		additional pcs needed not included in Base Order	Base Order Custom 1x2 to match cove C9 area remaining	10 + 27.5 + 10 x 4' If of coved ceiling Panels 1x2 additional pcs needed not included in Base Order 91 p NOTE: Tin ceiling tiles are nailed to existing wood stripping. This price does not include replacing any stripping	Remove and replace Insulation above ceiling tiles Remove and replace Insulation	Install and remove shoring of ceiling joist a lnstall 6 - 2x4 plates 12'(2-12' walls) b Install 2x4-14' studs 16" on Center(2-12' walls) c Install 2x4 plates (1-27.5' wall) d Install 2x4-14' studs 16" on Center(2-12' walls) e Install 2-2x6 headers @ 1 location f Carpenter After hrs g Labor After hrs
4 @		۵		O	ص ه	· σ - ψ σ υ ο φ - ω
7					z	Z

page 17 of 18	\$384.50	\$153.80	and a A bandwards	\$60.00	\$80.00	ania m	\$334.08	\$334.08	\$13,386.51	\$1,104.39	\$15,837.35	\$1,583,74	\$17,421.09	\$1,742,11	\$19,163.20
				\$20.00	\$20.00		\$334.08	\$334.08		8.25% sales tax		10%OH		10%P	
				\$5.00	\$5.00		\$27.84	\$27.84		8.25%s					
	\$384.50	\$153.80		\$40.00	\$60.00										
	38.45				\$15.00										
	10 pcs	4 pcs	4 pcs	4 units	4 units		12 hrs	12 hrs		rogresses	st ten				
Sistering of existing bowed diagonal 2x6 members	a 2x6-14	b Bridging 2x6-14	c Anchors	2-1/2"x5" round threaded rods	Epoxy	Raise existing joist to match existing	Carpenter After hrs	Labor After hrs		Note: This estimate is subject to change as work progresses	assuming the structural damage is limited to the first ten	foot. Therefore, supplements may be required.			
	·V							******			71.40 - ·	-			

0	Replace damaged ceiling tiles and insulation in dining and attic areas	sulation	in dir	ing and	dattic ar	eas		
(CERNETTE)	(Damaged ceiling tiles are within the area 16' from the East wall and from 10' from the South wall to the North wall	e East wall	and fro	im 10' fron	the South	wall to the	North wall	e de la composição de l
	and the area 16' wide down the east wall and 16' wide across the back wall)	e across th	e back	wall)				
add jourseld	East wall ceiling 16x68=	1088 sf	Sţ.					
Fagurd f, 1999 to a	North wall ceiling (26'-16')=10' x 16'=	160 sf	' રહે					
meem		1248 ST	SI					
	Install shoring inside dining area							en e
item		Onty	type unit	•	Material	unit	Labor	subtotal
0	Remove contents in dining and kitchen areas	•	ı 1					
(O	a Manipulation of contents after hrs	48 hrs	hrs			\$27.84	\$27.84 \$1,336.32	\$1,336.32
<u></u>	Temporary storage 8x40	-	1 mo	\$645.00	\$645.00			\$645.00
0	Set up scaffolding to remove and install Ceiling tiles in dining and kitchen	n dining an	nd kitche	Ë				Die Aventeim
w		inc C7 hr	hr			\$27.84	\$55.68	\$0.00
<u></u>	b Scaffold-per section 5x5@2	inc C7 per w	per w	\$48.00	\$96.00			\$0.00

\$122,321.95	<u>u</u>	Total	ffices: schon.	Note: This Estimate is subject to increase in cost if there is additional damage found during repairs or construction.
\$38,001.85				
\$3,454,71	10%P			
\$3,140,65	10%OH			
\$31,406.49			٠,	to this work.
\$29,012.92 \$2,393,57	8.25% sales tax		ili. Once repairs polement	ran through the building and all along the back wall. Once repairs begin further damage may be found requiring a supplement
			Ssment, 3/20/15	Pg 3 paragraph 1 of supplemental Structural Assessment, 3/20/15 As a result of the water test it was found the water
\$3,806.40	\$1.85 \$2,308.80	\$1.20 \$1,497.60	1248 sf	Remove and replace Insulation above ceiling tiles a Remove and replace Insulation
\$11,862.00 \$11,363.20	\$8.00 \$1,600.00 \$8.00 \$1,696.00	\$51.31 \$10,262.00 \$45.60 \$9,667.20	S S	Remove and reinstall Tin Ceiling Panel Custom 1x2 cove tile to match existing Custom 2x2 to match existing 212 tilt NOTE: Tin ceiling tiles are nailed to existing wood stripping. This price does not include replacing any stripping
page 18 of 18			id shoring	Detach and replace ceiling tiles to allow access and shoring